

Emotron FDU and VFX AC drives

Emotron VFX/FDU48-2P5-2Y to 038-2Y







Quick Start Guide English



Emotron FDU and VFX AC drives

Emotron VFX/FDU48-2P5-2Y to 038-2Y

QuickStartGuide - English

Document number: 01-5673-01

Edition: r2

Date of release: 20 December 2016

© Copyright CG Drives & Automation Sweden AB 2015-2016. CG Drives & Automation retains the right to change specifications and illustrations in the text, without prior notification. The contents of this document may not be copied without the explicit permission of CG Drives & Automation Sweden AB.

Contents

	Contents	1
	Safety Instructions	3
1.	General	6
1.1	Model Explanation	6
2.	Electrical specifications	9
2.1 2.2 2.3	Electrical specifications related to mode Brake resistor Fuses and input current	15
2.4	Mounting	
2.5	Remove dust cover	19
2.6	Remove Keypad and Cover	20
3.	Cable connections	22
3.1	Mains and motor cables	22
3.2	Connecting the Control Signals	26
4.	Inputs configuration with the jumpers	30
5.	Mount the cover	31
5.1	Mount the keypad	32
6.	Getting started	33
6.1	Using the function keys	34
6.2	Remote control	35
	Menu list	39

1

Quick Start Guide

Safety Instructions

Handling the AC drive

Installation, commissioning, demounting, taking measurements, etc. of or on the AC drive may only be carried out by personnel technically qualified for the task.

A number of national, regional and local regulations govern handling, storage and installation of the equipment. Always observe current rules and legislation.

Opening the AC drive



WARNING!

Always switch off the mains voltage before opening the AC drive and wait at least 10 minutes to allow the capacitors to discharge.

Always take adequate precautions before opening the AC drive. Although the connections for the control signals and the switches are isolated from the main voltage, do not touch the control board when the AC drive is switched on.

Precautions to be taken with a connected motor

If work must be carried out on a connected motor or on the driven machine, the mains voltage must always be disconnected from the AC drive first. Wait at least 10 minutes before starting work.

Earthing

The AC drive must always be earthed via the mains safety earth connection.

Earth leakage current



CAUTION!

This AC drive has an earth leakage current which does exceed 3.5 mA AC. Therefore the minimum size of the protective earth conductor must comply with the local safety regulations for

high leakage current equipment which means that according to the standard IEC61800-5-1 the protective earth connection must be assured by one of following conditions:

PE conductor cross-sectional area shall for phase cable size < 16 mm² (6 AWG) be >10 mm² Cu (16 mm² Al) or a second PE conductor with same area as original PE conductor.

For cable size above 16 mm² but smaller or equal to 35 mm² the PE conductor cross-sectional area shall be at least 16 mm².

For cables $>35~\text{mm}^2$ the PE conductor cross-sectional area must be at least 50 % of the used phase conductor.

When the PE conductor in the used cable type is not in accordance with the above mentioned cross-sectional area requirements, a separate PE conductor should be used to establish this.

Residual current device (RCD) compatibility

This product causes a DC current in the protective conductor. Where a residual current device (RCD) is used for protection in case of direct or indirect contact, only a Type B RCD is allowed on the supply side of this product. Use RCD of 300 mA minimum.

EMC Regulations

In order to comply with the EMC Directive, it is absolutely necessary to follow the installation instructions. All installation descriptions in this manual follow the EMC Directive.

Voltage tests (Megger)

Do not carry out voltage tests (Megger) on the motor, before all the motor cables have been disconnected from the AC drive.

Condensation

If the AC drive is moved from a cold (storage) room to a room where it will be installed, condensation can occur. This can result in sensitive components becoming damp. Do not connect the mains voltage until all visible dampness has evaporated.

Incorrect connection

The AC drive is not protected against incorrect connection of the mains voltage, and in particular against connection of the mains voltage to the motor outlets U, V and W. The AC drive can be damaged in this way.

Power factor capacitors for improving $\text{cos}\phi$

Remove all capacitors from the motor and the motor outlet.

Precautions during Autoreset

When the automatic reset is active, the motor will restart automatically provided that the cause of the trip has been removed. If necessary take the appropriate precautions.

Transport

To avoid damage, keep the AC drive in its original packaging during transport. This packaging is specially designed to absorb shocks during transport.

IT Mains supply

The AC drives can be modified for an IT mains supply, (non-earthed neutral), please contact your supplier for details.

Alarms

Never disregard an alarm. Always check and remedy the cause of an alarm.

DC-link residual voltage



WARNING!

After switching off the mains supply, dangerous voltage can still be present in the AC drive. When opening the AC drive for installing and/or commissioning activities, wait at least 10 minutes. In case of malfunction a qualified technician should check the DC-link or wait for one hour before dismantling the AC drive for repair.

General

Congratulations for choosing a product from CG Drives & Automation!

This is a Quick Start Guide providing brief information about how to install this AC drive and how to get started.

Before you start mounting and installation, please read and consider the Safety chapter first.

The software instruction manual you will find in the file archive on www.emotron.com. In the software instruction manual you will find detailed information for setting up and running this AC drive.

Instruction manuals for optional boards are also found in the file archive. All documentation is available on www.emotron.com.

1.1 Model Explanation

The Model shown on product label indicates the series name, applicable type of power supply, power class and hardware, etc. via the combination of numbers, symbols and letters.

. 7	8-023 2YCEB-AAVNI 0-480V 27.8A	N-NA 45 - 65Hz
Enclosure: IP20 Fuse, amb temp & ratin	23A	0-400Hz
		See instruction manual CE Trives & Automation Sweden AB

Fig. 1 Product label

1.1.1 Model Type code number

Fig. 2 gives an example of the type code numbering used on all AC drives. With this code number the exact type of the drive can be determined. This identification will be required for type specific information when mounting and installing. The code number is located on the product label, on the AC drive see Fig. 1.

Type code	FLD	48	-023	-2Y	С	Ε	В	_	Α	Α	٧	N	N	_	N	Α	_	_	-
Position No	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19

Fig. 2 Type code number

Table 1 Type code explanation

Position	Configuration	
1	AC drive type	FLD
2	Supply voltage	48=480 V mains
3	Rated current (A) continuous	-2P5=2.5 A - -038=38 A
4	Protection class	2Y=IP20
5	Control panel	C=Standard panel
6	EMC option	E=Standard EMC (2 nd Environment, Category C3) I=IT-Net
7	Brake chopper option	B=Chopper built in, standard
8		-=Not used
9	Brand label	A=Standard
10	Painted AC drive	A=Standard paint
11	Coated boards, option	V=Coated boards, standard

Table 1 Type code explanation

Position	Configuration				
12	Option position 1	N=No option			
13	Option position 2	E=Encoder- 2Y (micro) max 1 T=PTC-2Y (micro), max 1 I= Extended I/O-2Y (micro), max 2 S=Safe Stop-2Y (micro), max 1 R=RS232/485-2Y (micro), max 1 U= Standby supply-2Y(micro), max			
14		-= Not used			
15	Option position, communication	N=No option D=DeviceNet P=Profibus S=RS232/485 M=Modbus/TCP E= EtherCAT A=Profinet IO 1-port B=Profinet IO 2-port G=EtherNet/IP 2-port			
16	Software type	A=Standard			
17		-= Not used			
18		-= Not used			
19	Approval/certification	-=CE approved			

Electrical specifications

2. Electrical	specifications				
General					
Mains voltage: Mains frequency: Input power factor: Output voltage: Output frequency: Output switching frequency: Efficiency at nominal load:	3 phase 230 - 480 V +10/-15 % (-10 % at 230 V) 45 to 65 Hz 0.7 - 0.8 0-Mains supply voltage: 0-400 Hz 3 kHz, adjustable 1,5-6 kHz ≥93 % for frame sizes A3 and B3 >95 % for frame size C3				
Control signal inputs: Ana	alogue (differential)				
Analogue Voltage/current: Max. input voltage: Input impedance: Resolution: Hardware accuracy: Non-linearity	0-±10 V/0-20 mA via switch +30 V/30 mA 20 kOhm (voltage) 250 kOhm (current) 11 bits + sign 1% type + 1 ½ LSB fsd 1½ LSB				
Digital:					
Input voltage: Max. input voltage: Input impedance: Signal delay:	High: >9 VDC, Low: <4 VDC +30 VDC <3.3 VDC: 4.7 kOhm ≥3.3 VDC: 3.6 kOhm ≤8 ms				
Control signal outputs: Ar	_				
Output voltage/current: Max. output voltage: Short-circuit current (∞): Output impedance: Resolution: Maximum load impedance for current Hardware accuracy: Offset: Non-linearity:	0-10 V/0-20 mA via software setting +15 V @5 mA cont. +15 mA (voltage), +140 mA (current) 10 Ohm (voltage) 10 bit 500 Ohm 1.9% type fsd (voltage), 2.4% type fsd (current) 3 LSB 2 LSB				
Digital					
Output voltage: Shortcircuit current(∞):	High: $>20 \text{ V}_{DC}$ @50 mA, $>23 \text{ V}_{DC}$ open Low: $<1 \text{ V}_{DC}$ @50 mA 100 mA max (together with $+24 \text{ V}_{DC}$)				

Quick Start Guide

Relays	
Contacts	0.1 – 2 A/Umax 250 V _{AC} or 42 V _{DC}
References	
+10 VDC	+10 V _{DC} @10 mA Short-circuit current +30 mA max - 10 V _{DC} @10 mA
-10 VDC +24 VDC	+24 V _{DC} Short-circuit current +100 mA max (together with Digital Outputs)

2.1 Electrical specifications related to mode **Emotron VFX1**

Table 2 Typical motor power at mains voltage 400 V. AC drive main voltage range 380 - 480 V.

Model	Model Max.		ty (120%, ry 10 min)	Heavy du 1 min e m	Frame	
Widdel	output current [A]*	Power @400 V [kW]	Rated current [A]	Power @400 V [kW]	Rated current [A]	size
VFX48-2P5-2Y	3.8	0.75	2.5	0.55	2.0	
VFX48-3P4-2Y	5.1	1.1	3.4	0.75	2.7	
VFX48-4P1-2Y	6.2	1.5	4.1	1.1	3.3	
VFX48-5P6-2Y	8.4	2.2	5.6	1.5	4.5	А3
VFX48-7P2-2Y	10.8	3.0	7.2	2.2	5.8	
VFX48-9P5-2Y	14.3	4.0	9.5	3.0	7.6	
VFX48-012-2Y	18.0	5.5	12	4.0	9.6	
VFX48-016-2Y	24	7.5	16	5.5	12.8	В3
VFX48-023-2Y	34.5	11	23	7.5	18.4	دم
VFX48-032-2Y	46.5	15	31	11	24.8	C3
VFX48-038-2Y	56	18.5	38	15	30.4	03

^{*} Available during limited time and as long as allowed by drive temperature.

Table 3 Typical motor power at mains voltage 460 V. AC drive main voltage range 380 - 480 V.

Model Max.		(120%, 1	al duty min every min)	Heavy du 1 min eve	Frame	
iviodei	output current [A]*	Power @460 V [hp]	Rated current [A]	Power @460 V [hp]	Rated current [A]	size
VFX48-2P5-2Y	3.8	1	2.5	0.75	2.0	
VFX48-3P4-2Y	5.1	1.5	3.4	1	2.7	
VFX48-4P1-2Y	6.2	2	4.1	1.5	3.3	
VFX48-5P6-2Y	8.4	3	5.6	2	4.5	А3
VFX48-7P2-2Y	10.8	4	7.2	3	5.8	
VFX48-9P5-2Y	14.3	5	9.5	4	7.6	
VFX48-012-2Y	18.0	7.5	12	5	9.6	
VFX48-016-2Y	24	10	16	7.5	12.8	В3
VFX48-023-2Y	34.5	15	23	10	18.4	ъз
VFX48-032-2Y	46.5	20	31	15	24.8	C3
VFX48-038-2Y	56	25	38	20	30.4	C3

^{*} Available during limited time and as long as allowed by drive temperature.

Emotron FDU

Table 4 Typical motor power at mains voltage 400 V. AC drive main voltage range 380 - 480 V.

Model	Max	Normal duty (120%, 1 min every 10 min)			Heavy duty (150%, 1 min every 10 min)			
Wiodel	output current [A]*	Power @400 V [kW]	Rated current [A]	Power @400 V [kW]	Rated current [A]	size		
FDU48-2P5-2Y	3.0	0.75	2.5	0.55	2.0			
FDU48-3P4-2Y	4.1	1.1	3.4	0.75	2.7			
FDU48-4P1-2Y	4.9	1.5	4.1	1.1	3.3			
FDU48-5P6-2Y	6.7	2.2	5.6	1.5	4.5	А3		
FDU48-7P2-2Y	8.6	3.0	7.2	2.2	5.8			
FDU48-9P5-2Y	11.4	4.0	9.5	3.0	7.6			
FDU48-012-2Y	14.4	5.5	12	4.0	9.6			
FDU48-016-2Y	19.2	7.5	16	5.5	12.8	В3		
FDU48-023-2Y	27.6	11	23	7.5	18.4	ъз		
FDU48-032-2Y	37.2	15	31	11	24.8	C3		
FDU48-038-2Y	45.6	18.5	38	15	30.4	C3		

^{*} Available during limited time and as long as allowed by drive temperature.

Table 5 Typical motor power at mains voltage 460 V. AC drive main voltage range 380 - 480 V.

Model	Max.		ity (120%, ry 10 min)	1 min e	ity (150%, every 10 in)	Frame
Wiodel	output current [A]*	Power @460 V [hp]	Rated current [A]	Power @460 V [hp]	Rated current [A]	size
FDU48-2P5-2Y	3.0	1	2.5	0.75	2.0	
FDU48-3P4-2Y	4.1	1.5	3.4	1	2.7	
FDU48-4P1-2Y	4.9	2	4.1	1.5	3.3	
FDU48-5P6-2Y	6.7	3	5.6	2	4.5	А3
FDU48-7P2-2Y	8.6	4	7.2	3	5.8	
FDU48-9P5-2Y	11.4	5	9.5	4	7.6	
FDU48-012-2Y	14.4	7.5	12	5	9.6	
FDU48-016-2Y	19.2	10	16	7.5	12.8	В3
FDU48-023-2Y	27.6	15	23	10	18.4	ъз
FDU48-032-2Y	37.2	20	31	15	24.8	C3
FDU48-038-2Y	45.6	25	38	20	30.4	C3

^{*} Available during limited time and as long as allowed by drive temperature.

Brake resistor 2.2

These AC drives are as standard equipped with built in Brake chopper and connection for DC+/DC-. The brake resistor must be mounted outside the AC drive

Table 6 Minimum resistance depending on drive size and supply voltage.

Туре	Rmin if supply 380-415 V _{AC} [Ohm]	Rmin if supply 440-480 V _{AC} [Ohm]
VFX/FDU48-2P5-2Y	120	150
-3P4-2Y	120	150
-4P1-2Y	120	150
-5P6-2Y	91	120
-7P2-2Y	91	120
-9P5-2Y	68	91
-012-2Y	51	68
-016-2Y	36	51
-023-2Y	27	33
-032-2Y	18	24
-038-2Y	15	20

2.3 Fuses and input current

2.3.1 According to IEC ratings

Use mains fuses of the type gL/gG conforming to IEC 269 or breakers with similar characteristics. Check the equipment first before installing the glands.

Max. Fuse = maximum fuse value that still protects the AC drive and upholds warranty.

NOTE: The dimensions of fuse and cable cross-section are dependent on the application and must be determined in accordance with local regulations.

Table 7 Fuses and input current

	Nominal in	Maximum	
Model	with DC Choke [A]	without DC Choke [A]	value fuse [A]
VFX/FDU48-2P5-2Y	2.0	3.5	10
-3P4-2Y	2.5	4.5	10
-4P1-2Y	2.7	4.7	10
-5P6-2Y	4.5	6.1	16
-7P2-2Y	6.0	9.0	16
-9P5-2Y	8.1	11.0	25
-012-2Y	10.2	15.3	25
-016-2Y	14.0	20.0	32
-023-2Y	20.4	27.8	40
-032-2Y	27.0	37.0	63
-038-2Y	34.0	46.0	63

2.4 Mounting




Fig. 3 Dimensions

Table 8 Dimensions

Frame size	Dim. H1/H2/H3 x W x D mm	Dim. H1/H2/H3 x W x D in	Weight kg (lbs)
A3	220/245/287 x 120 x 169	8.7/9.6/11.3 x 4.7 x 6.7	2.6 (5.7)
В3	255/280/325 x 145 x 179	9.8/11/12.8 x 5.7 x 7	3.9 (8.6)
C3	335/365/407 x 190 x 187	13.2/14.4/16 x 7.5 x 7.4	5 (11)

2.4.1 Cooling /cabinet mounting

If the AC-drive is installed in a cabinet, the rate of airflow supplied by the cooling fans must be taken into consideration.

Frame size	Emotron AC drive model	Flow rate m ³ /hour
A3	-2P5 to -012	39
В3	-016 to -023	89
C3	-032 to -038	177




Fig. 4 Mounting dimensions.

Table 9 Mounting dimensions

Frame size	A mm (in)	B mm (in)	C mm (in)	D mm (in)	Ø mm (in)
A3	80 (3.15)	233 (9.17)	6 (0.24)	20 (0.79)	5.5 (0.20)
В3	105 (4.13)	268 (10.55)	6 (0.24)	20 (0.79)	5.5 (0.20)
C3	120 (4.72)	353 (13.89)	6 (0.24)	35 (1.38)	6 (0.24)

Remove dust cover 2.5

Remove the dust cover when installing the AC drive in a cabinet. see Fig. 5.




Fig. 5 Remove the dust cover

2.6 Remove Keypad and Cover

In order not to damage the keypad terminal plug, remove the keypad before you remove the front cover.

2.6.1 Remove the keypad

Press the quick-release latch of keypad as indicated by number "1" in Fig. 6, then pull the keypad out to release as indicated by "2".




Fig. 6 Remove the keypad

Open the Cover 2.6.2

First remove the keypad according to Figure 6.

Frame size A3 and B3

Use a flat screwdriver to press in the quick-release latches at the bottom of the cover to easily remove the cover, as indicated by "2", pull the cover out to release, as indicated by number "3".

Frame size C3

Loosen the captive cover screw with your fingers, as indicated by number "1" in Fig. 7. Then use a flat screwdriver to press in the quick-release latches at the bottom of the cover to easily remove the cover, as indicated by "2", pull the cover out to release, as indicated by number "3".




Fig. 7 Open the cover.

3. Cable connections

3.1 Mains and motor cables

Dimension the mains and motor cables according to local regulations. The cable must be able to carry the AC drive load current.

3.1.1 Cable connection data for mains, motor and PE cables according to IEC ratings

Table 10 Cable connector range and tightening torque according to IEC ratings.

		Cable cross	Cable cross section connector range			
Model	Frame	Mains, n	Cable tune			
VFX/FDU48	size	Cable area mm ² /AWG	Screw	Tightening torque Nm /Lb-In	Cable type	
-2P5-2Y		2.5 / 13	M3.5	0.8/7		
-3P4-2Y		2.57 15	1013.3	0.0/1		
-4P1-2Y						
-5P6-2Y	А3	2.5 / 13				
-7P2-2Y			M4 1.4		0 (0)	
-9P5-2Y		4 / 11			Copper (Cu) 75°C	
-012-2Y		4/11			75 0	
-016-2Y	В3	(/ 0		/ 0		
-023-2Y	DS	6/9				
-032-2Y	C3	6/9	M5	2.7/24		
-038-2Y	C3	0/9	UNIO	2.1124		

312 Mains and motor cables connection

Connect the mains and motor cables according to Fig. 8. Secure the cables with the EMC/strain relief clamps.

There are two Ferrites included in delivery, one ferrite for Mains wires and the other ferrite for the motor wires.

Lead the PE/earth wires directly to the Earth connection screws (not through the ferrites).


Mains cable

Use one ferrite for Mains wires L1, L2, L3. Wind the wires once around the ferrite. Connect the wires to the terminals R/L1, S/L2 and T/L3.

Motor cable

- Connect the motor cable screen to the clamp according to Fig. 8.
- Use the other ferrite for the motor wires U, V and W, let the wires go straight through the ferrite. Connect the wires to the terminals U/T1, V/T2 and W/T3.

Secure all other cables such as DC or brake cables with tie wraps by using the slots.



Mains and motor cable connections Fig. 8

Main Circuit Terminals




Fig. 9 Main circuit terminals.

Table 11 Terminal markings

Terminal marks	Designation and function of terminals
R/L1, S/L2, T/L3	Three-phase AC input terminals.
⊕1, ⊕2/B1	DC reactor connection terminals. Connected to +2/B1 with a jumper as factory default
⊕2/B1, B2	Braking resistor connection terminals
B2, ⊝	DC input terminals of externally mounted brake unit
⊕1, ⊝	DC power supply input terminals
U/T1, V/T2, W/T3	Three-phase AC output terminals
PE 🖶	Ground terminals, PE




Fig. 10 Typical wiring example for 3-phase Mains supply



WARNING!

In order to work safely, the mains earth must be connected to PE and the motor earth to \perp .

3.2 Connecting the Control Signals

3.2.1 Cables

Always use screened control signal cables. The standard control signal connections are suitable for stranded flexible wire up to 1.5 mm² (AWG15) and for solid wire up to 2.5 mm² (AWG13).

Table 12 Cable connector range and tightening torque

Cable cross section connector range mm ² / AWG	Screw	Tightening torque (Nm/Lb-In)
1.5 - 2.5 / 15-13	M3	0.5 / 4.4

Screening

Connect the cable screen to the Earthing screw see Fig. 11.

For all signal cables the best results are obtained if the screen is connected to both ends: the AC drive side and at the source (e.g. PLC, or computer).

It is strongly recommended that the signal cables be allowed to cross mains and motor cables at a 90° angle. Do not let the signal cable go in parallel with the mains and motor cable.

NOTE: The screening of control signal cables must comply with the immunity levels given in the EMC Directive (reduction of noise level).

NOTE: The control cables must be separated from motor and mains cables.




Fig. 11 Connecting the control signals and screen connection.




Fig. 12 Terminals for control signal connections and Jumpers S1 - S4,

3.2.2 Terminal connections

Table 13 describes the default functions for the signals. The inputs and outputs are programmable for other functions as described in the main instruction manual.

NOTE: The maximum total combined current for outputs 11, 20 and 21 is 100 mA.

NOTE: It is possible to use external 24 V DC if connection to Common (15).

Table 13 Control signals default functions

	1	
Terminal	Name	Function (Default)
Outputs		
1	+10 V	+10 V _{DC} supply voltage
6	-10 V	-10 V _{DC} supply voltage
7	Common	Signal ground
11	+24 V	+24 V _{DC} supply voltage
12	Common	Signal ground
15	Common	Signal ground
Digital inputs		
8	Digln 1	RunL (reverse)
9	DigIn 2	RunR (forward)
10	DigIn 3	Off
16	DigIn 4	Off
17	DigIn 5	Off
18	DigIn 6	Off
19	DigIn 7	Off
22	DigIn 8	RESET

Table 13 Control signals default functions

Terminal	Name	Function (Default)
Digital outputs		
20	DigOut 1	Ready
21	DigOut 2	No trip - FDU Brake - VFX
Analogue inp	uts	
2	Anln 1	Process Ref
3	Anln 2	Off
4	Anln 3	Off
5	Anln 4	Off
Analogue out	puts	
13	AnOut 1	Min speed to max speed
14	AnOut 2	0 to max torque
Relay outputs	5	
31	N/C 1	Relay 1 output
32	COM 1	Trip, active when the AC drive is in a TRIP condi-
33	N/O 1	tion.
41	N/C 2	
42	COM 2	Relay 2 output Run, active when the AC drive is started.
43	N/O 2	
51	COM 3	Relay 3 output
52	N/O 3	Off

NOTE: N/C is opened when the relay is active and N/O is closed when the relay is active.



WARNING!

The relay terminals 31-52 are single isolated. Do NOT mix SELV voltage with e.g. 230 V_{AC} on these terminals.

4. Inputs configuration with the jumpers

The jumpers S1 to S4 are used to set the input configuration for the 4 analogue inputs AnIn1, AnIn2, AnIn3 and AnIn4 as described in table 14. See Fig. 12 for the location of the jumpers.

Table 14 Jumper settings

Input	Signal type	Jumper
Anin1	Voltage	S1 U
	Current (default)	S1 I U
Anin2	Voltage	S2 I U
7 11112	Current (default)	S2 U
AnIn3	Voltage	S3 I U
JANINO .	Current (default)	S3 U
AnIn4	Voltage	S4 I U
, , , , , , , , , , , , , , , , , , , ,	Current (default)	S4 I U

5. Mount the cover

Frame size A3 and B3

On the completion of wiring, insert the quick-release latches at the upper part of the cover into the grooves in the centre housing as indicated by number "1" in Fig. 13, then push in the lower part of the cover as indicated by "2". A clicking noise indicates that the cover is correctly attached.

Frame size C3

On the completion of wiring, insert the quick-release latches at lower part of the cover, fitting the screw and the quick-release latches into the grooves in the centre housing as indicated by number "1" in Fig. 13, then push in the upper part of the cover as indicated by "2". A clicking noise indicates that the cover is correctly attached. Tighten the screw with your fingers (at position 1).




Fig. 13 Mount the cover.

5.1 Mount the keypad

Slightly tilt the keypad in the direction as indicated by number "1" in Fig. 6 and align it to quick-release latches at lower part of keypad bracket, then press it in as indicated by "2". A clicking noise indicates that the cover is correctly attached.




Fig. 14 Mount the keypad

6. Getting started

6.0.1 Control connection example, remote control




Fig. 15 Connection example for remote control.

Table 15 Description of used terminals.

Terminal	Name	Function (Default)	
2	AnIn 1	Process reference, default: speed	
7	Common	Signal ground	
9	DigIn 2	RunR; rotation right	
11	+24V	+24VDC Supply voltage	
12	Common	Signal ground (If desired)	
13	AnOut 1	Min speed to max speed (If desired)	
14	AnOut 2	0 to max torque (If desired)	
22	DigIn 8	Reset	

6.1 Using the function keys





Fig. 16 Example of menu navigation when entering motor voltage



6.2 Remote control

In this example external signals are used to control the AC drive/motor.

A standard 4-pole motor for 400 V, an external start button and a reference value will also be used.

Switch on the mains

Once the mains is switched on, the internal fan in the AC drive will run for 5 seconds (In frame size A3 the fan runs continuously).

Set the Motor Data

Enter correct motor data for the connected motor. The motor data is used in the calculation of complete operational data in the AC drive.

Change settings using the keys on the control panel.

Menu [100], Preferred View is displayed when started.

- 1. Press to display menu [200], Main Setup.
- 2. Press and then to display menu [220], Motor Data.
- 3. Press to display menu [221] and set motor voltage.
- 4. Change the value using the + and keys. Confirm with 🔛.
- 5. Set motor frequency [222].
- 6. Set motor power [223].
- 7. Set motor current [224].
- 8. Set motor speed [225].
- 9. Set power factor ($\cos \varphi$) [227].
- 10. Select supply voltage level used [21B]
- 11. Set Motor type [22I]
- 12. [229] Motor ID run: Choose Short, confirm with ENTER and give start command Ω .
 - The AC drive will now measure some motor parameters. The motor makes some beeping sounds but does not rotate. When the ID run is finished after about one minute ("Test Run OK!" is displayed), press to continue.
- 13. Use AnIn1 as input for the reference value. The default range is 4-20 mA. If you need a 0-10 V reference value, change switch (S1) on control board.

- 14. Switch off power supply.
- 15. Connect digital and analogue inputs/outputs as in figure below.




Fig. 17 Connecting reference signal

- 16. Ready!
- 17. Switch on power supply.

Run the AC drive

Now the installation is finished, and you can press the start button to start the motor. This test run will show that the main connections are OK and that the motor will run with the load.

6.2.1 Default toggle loop

Figure 18 shows the default toggle loop. This loop contains the necessary menus that need to be set before starting. Press Toggle to enter menu [211] then use the Next key to enter the sub menus [212] to [21A] and enter the parameters. When you press the Toggle key again, menu [221] is displayed.




Fig. 18 Default toggle loop

6.2.2 Overview of the main menu

[100]	Preferred view. Displayed at power-up. Shows actual values (default: speed and torque).
[200]	Main Setup. Main settings to get the inverter operable e.g. motor data, autoreset and language.
[300]	Process and Application parameters. Settings more relevant to the application such as Reference Speed, torque limitations, PID control settings, etc.
[400]	Shaft power monitor and process protection. The monitor function enables the AC drive to be used as a load monitor to protect machines and processes against mechanical overload and underload.
[500]	Inputs/outputs and virtual connections. All settings for analogue and digital inputs and outputs.
[600]	Logical functions and timers. All settings for conditional signals are entered here.
[700]	View operation and status. Viewing all the operational data like frequency, load, power, current, etc.
[800]	View Trip log. Viewing the last 10 trips in the trip memory.
[900]	Service information and AC drive data. Electronic type label for viewing the software version and AC drive type.

Menu list

On our home page in the download area, you could find a "Communication information" list and a list to note Parameter set information .

					Factory setting	Note/ Customer
100	Prefe	erred \	√iew		-	
1	110	1st L	ine		Process Val	
	120	2nd	Line		VFX: Torque FDU: Current	
200	Main	Setu	р			•
	210	Oper	ation			
		211	Langu	age	English	
		212	Select	Motor	M1	
		213	Drive N	Mode	VFX: Speed FDU: V/Hz	
		214	Ref Co	ontrol	Remote	
		215	Run/S	tp Ctrl	Remote	
		216	Reset	Ctrl	Remote	
		217	Local/	Rem		•
			2171	LocRefCtrl	Standard	
			2172	LocRunCtrl	Standard	
		218	Lock (Code?	0	
		219	Rotatio	on	R+L	
		21A	Level/I	Edge	Level	
		21B	Supply	y Volts	Not Defined	
		21C	Supply	у Туре	AC Supply	
	220	Moto	r Data			
		221	Motor	Volts	U _{NOM} V	
		222	Motor	Freq	50Hz	
		223	Motor	Power	(P _{NOM}) W	
		224	Motor	Curr	(I _{MOT}) A	
		225 Motor Speed226 Motor Poles227 Motor Cosφ		Speed	(n _{MOT}) rpm	
				Poles	4	
				Cosφ	Cos? _{NOM}	
		228 Motor Vent		Vent	Self	
		229 Motor ID-Run		ID-Run	Off	
		22A	Motor	Sound	F	FDU only
		22B	Encod	er	Off	
		22C	Enc Pu	ulses	1024	

22D Enc Speed Orpm FDU only					Footom: cotting	Note/ Customer
22E					Factory setting	Note/ Customer
22E1 PWM Fswitch 3.00 kHz FDU only					0rpm	
22E2 PWM Mode Standard FDU only		22E				
22E3 PWM Random Off FDU only					3.00 kHz	,
22F Enc Puls Ctr 0			22E2	PWM Mode	Standard	FDU only
22G Enc Fault	_		22E3	PWM Random	Off	FDU only
22G1 Enc F Delay Off		22F	Enc Pu	uls Ctr	0	
22G2 Enc F Band 10% 22G3 Max EncFCtr 0.000s		22G	Enc Fa	nult		
22G3 Max EncFCtr 0.000s 22H Phase order Normal 22I Motor type Async VFX only 230 Mot Protect 231 Mot I ² t Type Trip 232 Mot I ² t Curr 100% 233 Mot I ² t Time 60s 234 Thermal Prot Off 235 Motor Class F 140°C 240 Set Handling 241 Select Set A 242 Copy Set A>B 243 Default>Set A 244 Copy to CP No Copy 245 Load from CP No Copy 250 Autoreset 251 No of Trips 0 252 Overtemp Off 253 Overvolt D Off 254 Overvolt G Off 255 Overvolt G Off 256 Motor Lost Off 256 Motor Lost Off 256 Motor Lost Off 257 Overvolt Off 258 Overvolt Off 259 Overvolt Off 250 Overvolt Off 250 Overvolt Off 250 Overvolt Off 251 Overvolt Off 252 Overvolt Off 253 Overvolt Off 256 Motor Lost Off 257 Overvolt Off 258 Overvolt Off 259 Overvolt Off 250 Overvolt Off 250 Overvolt Off 250 Overvolt Off 251 Overvolt Off 252 Overvolt Off 253 Overvolt Off 254 Overvolt Off 255 Overvolt Off 256 Overvolt Off 257 Overvolt Off 258 Overvolt Off 259 Overvolt Off 250 Overvolt Overvolt Overvolt 250 Over	-		22G1	Enc F Delay	Off	
22H Phase order Normal			22G2	Enc F Band	10%	
221 Motor type Async VFX only			22G3	Max EncFCtr	0.000s	
230 Mot Protect 231 Mot I²t Type Trip 232 Mot I²t Curr 100% 233 Mot I²t Time 60s 60s 234 Thermal Prot Off 235 Motor Class F 140°C 240 Set Handling 241 Select Set A 242 Copy Set A>B 243 Default>Set A 244 Copy to CP No Copy 245 Load from CP No Copy 245 Load from CP No Copy 250 Autoreset 251 No of Trips 0 252 Overtemp Off 253 Overvolt D Off 254 Overvolt G Off 255 Overvolt G Off 256 Motor Lost Off 257 Motor Lost Off 258 Motor Lost Off 256 Motor Lost Off 257 Motor Lost Off 258		22H	Phase	order	Normal	
231 Mot 2 Trip		221	Motor	type	Async	VFX only
232 Mot I ² t Curr 100%	230	Mot	Protect			
233 Mot I²t Time				* .	Trip	
234 Thermal Prot Off 235 Motor Class F 140°C 240 Set Handling 241 Select Set A 242 Copy Set A>B 243 Default>Set A 244 Copy to CP No Copy 245 Load from CP No Copy 250 Autoreset 251 No of Trips O 252 Overtemp Off 253 Overvolt D Off 254 Overvolt G Off 255 Overvolt Off 256 Motor Lost Off 256 Motor Lost Off 267 Overvolt Off 268 Overvolt Off 270 Overvolt Off 280 Overvolt Off 281 Overvolt Off 281 Overvolt Off 281 Overvolt Off 282 Overvolt Off 283 Overvolt Off 284 Overvolt Off 285 Overvolt Off 286 Overvolt Off 386 Overvolt Off 386 Overvolt Overvolt 3		232	Mot I ² t	: Curr	100%	
235 Motor Class F 140°C		233	Mot I ² t	Time	60s	
240 Set Handling 241 Select Set A 242 Copy Set A>B 243 Default>Set A 244 Copy to CP No Copy 245 Load from CP No Copy 250 Autoreset 251 No of Trips 0 252 Overtemp Off 253 Overvolt D Off 254 Overvolt G Off 255 Overvolt Off 256 Motor Lost Off		234	Therm	al Prot	Off	
241 Select Set		235	Motor	Class	F 140°C	
242 Copy Set A>B 243 Default>Set A 244 Copy to CP No Copy 245 Load from CP No Copy 250 Autoreset O 251 No of Trips O 252 Overtemp Off 253 Overvolt D Off 254 Overvolt G Off 255 Overvolt Off 256 Motor Lost Off	240	Set F	landling	1		•
243 Default>Set A 244 Copy to CP No Copy 245 Load from CP No Copy 250 Autoreset 251 No of Trips 0 252 Overtemp Off 253 Overvolt D Off 254 Overvolt G Off 255 Overvolt Off 256 Motor Lost Off	-	241	Select	Set	А	
244 Copy to CP No Copy 245 Load from CP No Copy 250 Autoreset 251 No of Trips 0 252 Overtemp Off 253 Overvolt D Off 254 Overvolt G Off 255 Overvolt Off 256 Motor Lost Off		242	Copy S	Set	A>B	
245 Load from CP No Copy 250 Autoreset 251 No of Trips 0 252 Overtemp Off 253 Overvolt D Off 254 Overvolt G Off 255 Overvolt Off 256 Motor Lost Off						
250 Autoreset 251 No of Trips		244	Copy t	о СР	No Copy	
251 No of Trips 0 252 Overtemp Off 253 Overvolt D Off 254 Overvolt G Off 255 Overvolt Off 256 Motor Lost Off		245	Load f	rom CP	No Copy	
252 Overtemp Off 253 Overvolt D Off 254 Overvolt G Off 255 Overvolt Off 256 Motor Lost Off	250	Auto	preset			•
253 Overvolt D Off 254 Overvolt G Off 255 Overvolt Off 256 Motor Lost Off	-	251	No of	Trips	0	
254 Overvolt G Off 255 Overvolt Off 256 Motor Lost Off		252	Overte	mp	Off	
255 Overvolt Off 256 Motor Lost Off		253	Overvolt G Overvolt Motor Lost Locked Rotor Power Fault		Off	
256 Motor Lost Off	ľ	254			Off	
	ľ	255			Off	
	ľ	256			Off	
25 / Locked Rotor Off	ľ	257			Off	
258 Power Fault Off	ľ	258			Off	
259 Undervoltage Off	ļ	259			Off	
25A Motor I ² t Off	ļ	-			Off	
25B Motor I ² t TT Trip	ļ	25B	Motor	I ² t TT	Trip	
25E PTC Off	ļ	25E	PTC		Off	
25F PTC TT Trip	ļ	25F	PTC T	Т	Trip	

				Factory setting	Note/ Customer
	25G	Ext Trip	0	Off	
	25H	Ext Trip TT		Trip	
	251	Com E	rror	Off	
	25J	Com E	rror TT	Trip	
	25K	Min Ala	arm	Off	
	25L	Min Ala	arm TT	Trip	
	25M	Max A	larm	Off	
	25N	Max A	larm TT	Trip	
	250	Over c	urr F	Off	
	25P	Pump		Off	
	250	Over s	peed	Off	
	25R	Ext Mo	ot Temp	Off	
	25S	Ext Mo	ot TT	Trip	
	25T	LC Lev	/el	Off	
	25U	LC Lev	vel TT	Trip	
	25V	Brk Fa	ult	Off	
	25W	Encod	er	Off	
	25X	Crane	Deviat	Off	VFX only
	25Y	Crane	Comm	Off	VFX only
260		I Com			
	261	Com T	- уре	RS232/485	
	262	RS232	2/485		
		2621	Baudrate	9600	
		2622	Address	1	
	263	Fieldbu	ıs		
		2631	Address	62	
			PrData Mode	Basic	
			Read/Write	RW	
			AddPrValue	0	
	264	Comm			
			ComFlt Mode	Off	
			ComFlt Time	0.5 s	
	265	Ethernet			
			IP Address	0.0.0.0	
		2652	MAC Address	00000000000	
		2653	Subnet Mask	0.0.0.0	
			Gateway	0.0.0.0	
		2655	DHCP	Off	

						_
					Factory setting	Note/ Customer
		266	FB Sig	nal		
			2661	FB Signal 1	0	
			2662	FB Signal 2	0	
			2663	FB Signal 3	0	
			2664	FB Signal 4	0	
			2665	FB Signal 5	0	
			2666	FB Signal 6	0	
			2667	FB Signal 7	0	
			2668	FB Signal 8	0	
			2669	FB Signal 9	0	
			266A	FB Signal 10	0	
			266B	FB Signal 11	0	
			266C	FB Signal 12	0	
				FB Signal 13	0	
			266E	FB Signal 14	0	
			266F	FB Signal 15	0	
			266G	FB Signal 16	0	
		269	FB Sta	itus		·
300	Proce	ess				
	310	Set/\	/iew ref		0rpm	
	320	Proc	Setting			
•		321	Proc S	ource	Speed	
		322	Proc U	Init	rpm	
		323	User U	Init	0	
		324	Proces	ss Min	0	
		325	Proces	ss Max	0	
		326	Ratio		Linear	
		327	F(Val) F	PrMin	Min	
		328	F(Val) F	PrMax	Max	
	330	Start	/Stop			
		331	Acc Ti	me	10.00s	
		332	Dec Ti	me	10.00s	
	İ	333	Acc M	otPot	16.00s	
	İ	334	Dec M	otPot	16.00s	
		335	Acc>N	lin Spd	10.00s	
		336	Dec <n< td=""><td>/lin Spd</td><td>10.00s</td><td></td></n<>	/lin Spd	10.00s	
		337	Acc Rr	mp	Linear	
		338	Dec Ri	mp	Linear	
						•

339 Start Mode 33A Spinstart Off 33B Stop Mode Decel 33C Brk Release 0.00s 33D Release Spd Orpm 33E Brk Engage 0.00s 33F Brk Wait 0.00s 33F Brk Wait 0.00s 33F Brk Wait 0.00s 33F Brk Wait 0.00s 33B Brk Fault 1.00s 33B Release Torque 0% 34D Speed 341 Min Speed Orpm 342 Stjc-MinSpd Off 343 Max Speed Sync Speed 344 SkipSpd 1 Lo Orpm 345 SkipSpd 1 Lo Orpm 346 SkipSpd 2 Lo Orpm 347 SkipSpd 2 Hi Orpm 348 Jog Speed 50rpm 350 Torques 351 Max Torque 120% 352 krR Comp Off 353 krR CompUsr O'f 353 krR CompUsr O'f 355 Max Power O'ff 360 Preset Ref 361 Motor Pot 362 Preset Ref 2 250 rpm 365 Preset Ref 4 750 rpm 366 Preset Ref 5 1000 rpm 367 Preset Ref 6 1250 rpm 368 Preset Ref 7 1500 rpm 369 Keyb Ref Mot Pot VFX only 372 Spd P Gain VFX only VFX only 371 Spd P Gain VFX only VFX only VFX only 372 Spd P Gain VFX only VFX only VFX only 372 Spd P Gain VFX only 372 Spd P Gain VFX only VFX only VFX only VFX only VFX only 372 Spd P Gain VFX only VF				Factory setting	Note/ Customer
338 Stop Mode Decel		339	Start Mode		
33C Brk Release 0.00s 33D Release Spd 0rpm 33E Brk Engage 0.00s 33F Brk Walt 0.00s 33F Brk Walt 0.00s 33G Vector Brake 0ff 33H Brk Fault 1.00s 33H Brk Fault 1.00s 33H Brk Fault 1.00s 33H Min Speed 0rpm 342 Stps-MinSpd 0rf 343 Max Speed Sync Speed 344 SkipSpd 1 Lo 0rpm 345 SkipSpd 1 Lo 0rpm 346 SkipSpd 2 Lo 0rpm 347 SkipSpd 2 Hi 0rpm 348 Jog Speed 50rpm 350 Torques 351 Max Torque 120% 352 IxR Comp 0ff 353 IxR CompUsr 0% 354 Flux optim 0rf 355 Max Power 0ff 360 Preset Ref 361 Motor Pot Non Volatile 362 Preset Ref 1 0 rpm 364 Preset Ref 2 250 rpm 365 Preset Ref 4 750 rpm 366 Preset Ref 5 1000 rpm 367 Preset Ref 6 1250 rpm 368 Preset Ref 7 1500 rpm 369 Keyb Ref Mot Pot 370 Spd Ctrl Pl VFX only 371 Spd Pl Auto Off VFX only 075		33A	Spinstart	Off	
33D Release Spd Orpm		33B	Stop Mode	Decel	
33E Brk Engage 0.00s 33F Brk Wait 0.00s 33G Vector Brake Off 33H Brk Fault 1.00s 33I Release Torque 0% 34I Min Speed Orpm 342 Stp <minspd 1="" 1000="" 120%="" 1250="" 1500="" 2="" 250="" 343="" 344="" 345="" 346="" 347="" 348="" 350="" 351="" 352="" 353="" 354="" 355="" 360="" 361="" 362="" 363="" 366="" 367="" 368="" 369="" 370="" 371="" 372="" 373="" 374="" 375="" 376="" 377="" 378="" 379="" 381="" 4="" 5="" 6="" 7="" 750="" auto="" comp="" compusr="" ctrl="" flux="" hi="" ixr="" jog="" keyb="" lo="" max="" mot="" motor="" non="" off="" off<="" only="" optim="" orpm="" ow="" pl="" pot="" power="" preset="" ref="" rpm="" skipspd="" sorpm="" spd="" speed="" sync="" td="" torque="" torques="" vfx="" volatile="" =""><td></td><td>33C</td><td>Brk Release</td><td>0.00s</td><td></td></minspd>		33C	Brk Release	0.00s	
33F Brk Wait 0.00s 33G Vector Brake Off 33H Brk Fault 1.00s 33I Release Torque 0% 340 Speed 341 Min Speed Orpm 342 Stp <minspd 1="" 1000="" 120%="" 1250="" 1500="" 2="" 250="" 343="" 344="" 345="" 346="" 347="" 348="" 350="" 351="" 352="" 353="" 354="" 355="" 360="" 361="" 362="" 363="" 366="" 367="" 368="" 369="" 370="" 371="" 372="" 375="" 376="" 377="" 378="" 379="" 4="" 5="" 50rpm="" 6="" 7="" 750="" auto="" comp="" compusr="" ctrl="" flux="" hi="" ixr="" jog="" keyb="" lo="" max="" mot="" motor="" non="" o%="" off="" onl<="" only="" optim="" orpm="" pl="" pot="" power="" preset="" ref="" rpm="" skipspd="" spd="" speed="" sync="" td="" torque="" torques="" vfx="" volatile="" =""><td></td><td>33D</td><td>Release Spd</td><td>Orpm</td><td></td></minspd>		33D	Release Spd	Orpm	
33G Vector Brake Off 33H Brk Fault 1.00s 33H Release Torque 0%		33E	Brk Engage	0.00s	
33H Brk Fault 1.00s 33I Release Torque 0% 340 Speed 341 Min Speed Orpm 342 Stp <minspd 1="" 1000="" 120%="" 1250="" 1500="" 2="" 250="" 343="" 344="" 345="" 346="" 347="" 348="" 350="" 351="" 352="" 353="" 354="" 355="" 360="" 361="" 362="" 363="" 365="" 366="" 367="" 368="" 369="" 370="" 4="" 5="" 50rpm="" 6="" 7="" 750="" comp="" compusr="" ctrl="" flux="" hi="" ixr="" jog="" keyb="" lo="" max="" mot="" motor="" non="" o%="" off="" only<="" optim="" orpm="" pl="" pot="" power="" preset="" ref="" rpm="" skipspd="" spd="" speed="" sync="" td="" torque="" torques="" vfx="" volatile=""><td></td><td colspan="2">9 9</td><td>0.00s</td><td></td></minspd>		9 9		0.00s	
331 Release Torque 0%		33G	Vector Brake	Off	
340 Speed Stp Speed Orpm 342 Stp Min Speed Sync Speed Sync Speed 343 Max Speed Sync Speed 344 SkipSpd 1 Lo Orpm 345 SkipSpd 2 Lo Orpm 346 SkipSpd 2 Hi Orpm 348 Jog Speed Sorpm StipSpd 2 Hi Orpm 348 Jog Speed Sorpm StipSpd 2 Hi Orpm Off StipSpd 2 Hi Orpm StipSpd 3 Hi Orpm St		33H	Brk Fault	1.00s	
341 Min Speed Orpm		331	Release Torque	0%	
342 Stp <minspd 0%="" 1="" 1000="" 120%="" 1250="" 1500="" 2="" 250="" 3="" 343="" 344="" 345="" 346="" 347="" 348="" 350="" 351="" 352="" 353="" 354="" 355="" 360="" 361="" 362="" 363="" 364="" 365="" 366="" 367="" 368="" 369="" 370="" 4="" 5="" 500="" 50rpm="" 6="" 7="" 750="" comp="" compusr="" ctrl="" flux="" hi="" ixr="" jog="" keyb="" lo="" max="" mot="" motor="" non="" off="" only<="" optim="" orpm="" pl="" pot="" power="" preset="" ref="" rpm="" skipspd="" spd="" speed="" sync="" td="" torque="" torques="" vfx="" volatile=""><td>340</td><td>Spee</td><td>ed</td><td></td><td></td></minspd>	340	Spee	ed		
343 Max Speed Sync Speed 344 SkipSpd 1 Lo Orpm 345 SkipSpd 2 Lo Orpm 346 SkipSpd 2 Lo Orpm 347 SkipSpd 2 Hi Orpm 348 Jog Speed 50rpm 350 Torques 351 Max Torque 120% 352 IxR Comp Off 353 IxR CompUsr O% 354 Flux optim Off 355 Max Power Off 360 Preset Ref 361 Motor Pot Non Volatile 362 Preset Ref 1 Orpm 363 Preset Ref 2 250 rpm 364 Preset Ref 3 500 rpm 365 Preset Ref 4 750 rpm 366 Preset Ref 5 1000 rpm 367 Preset Ref 6 1250 rpm 368 Preset Ref 7 1500 rpm 369 Keyb Ref Mot Pot 370 Spd Ctrl Pl VFX only		341	Min Speed	0rpm	
344 SkipSpd 1 Lo		342	Stp <minspd< td=""><td>Off</td><td></td></minspd<>	Off	
345 SkipSpd 1 Hi Orpm 346 SkipSpd 2 Lo Orpm 347 SkipSpd 2 Hi Orpm 348 Jog Speed 50rpm 350 Torques 351 Max Torque 120% 352 IxR Comp Off 353 IxR CompUsr O% 354 Flux optim Off 355 Max Power Off 360 Preset Ref 361 Motor Pot Non Volatile 362 Preset Ref 1 Orpm 363 Preset Ref 2 250 rpm 364 Preset Ref 3 500 rpm 365 Preset Ref 4 750 rpm 366 Preset Ref 5 1000 rpm 367 Preset Ref 6 1250 rpm 368 Preset Ref 7 1500 rpm 369 Keyb Ref Mot Pot 370 Spd Ctrl Pl VFX only		343	Max Speed	Sync Speed	
346 SkipSpd 2 Lo		344	SkipSpd 1 Lo	0rpm	
347 SkipSpd 2 Hi Orpm		345	SkipSpd 1 Hi	0rpm	
348 Jog Speed 50rpm		346	SkipSpd 2 Lo	0rpm	
350 Torques 351 Max Torque 120% 352 IxR Comp Off 353 IxR CompUsr 0% 354 Flux optim Off 355 Max Power Off 355 Max Power Off 360 Preset Ref 361 Motor Pot Non Volatile 362 Preset Ref 1 0 rpm 363 Preset Ref 2 250 rpm 364 Preset Ref 3 500 rpm 365 Preset Ref 4 750 rpm 366 Preset Ref 5 1000 rpm 367 Preset Ref 6 1250 rpm 368 Preset Ref 7 1500 rpm 369 Keyb Ref Mot Pot VFX only 371 Spd PI Auto Off VFX only		347	SkipSpd 2 Hi	0rpm	
351 Max Torque 120% 352 IxR Comp Off 353 IxR CompUsr O% 354 Flux optim Off 355 Max Power Off 355 Max Power Off 360 Preset Ref		348	Jog Speed	50rpm	
352 IxR Comp 353 IxR CompUsr 0% 354 Flux optim Off 355 Max Power Off 360 Preset Ref 361 Motor Pot Non Volatile 362 Preset Ref 1 0 rpm 363 Preset Ref 2 250 rpm 364 Preset Ref 3 500 rpm 365 Preset Ref 4 750 rpm 366 Preset Ref 5 1000 rpm 367 Preset Ref 6 1250 rpm 368 Preset Ref 7 1500 rpm 369 Keyb Ref Mot Pot VFX only	350	Torqu	ies		
353 IxR CompUsr 0% 354 Flux optim Off 355 Max Power Off 360 Preset Ref 361 Motor Pot Non Volatile 362 Preset Ref 1 0 rpm 363 Preset Ref 2 250 rpm 364 Preset Ref 3 500 rpm 365 Preset Ref 4 750 rpm 366 Preset Ref 5 1000 rpm 367 Preset Ref 6 1250 rpm 368 Preset Ref 7 1500 rpm 369 Keyb Ref Mot Pot 370 Spd Ctrl Pl VFX only		351	Max Torque	120%	
354 Flux optim Off		352	IxR Comp	Off	
355 Max Power Off 360 Preset Ref 361 Motor Pot Non Volatile 362 Preset Ref 1 0 rpm 363 Preset Ref 2 250 rpm 364 Preset Ref 3 500 rpm 365 Preset Ref 4 750 rpm 366 Preset Ref 5 1000 rpm 367 Preset Ref 6 1250 rpm 368 Preset Ref 7 1500 rpm 369 Keyb Ref Mot Pot 370 Spd Ctrl Pl VFX only		353	IxR CompUsr	0%	
360 Preset Ref 361 Motor Pot Non Volatile 362 Preset Ref 1 0 rpm 363 Preset Ref 2 250 rpm 364 Preset Ref 3 500 rpm 365 Preset Ref 4 750 rpm 366 Preset Ref 5 1000 rpm 367 Preset Ref 6 1250 rpm 368 Preset Ref 7 1500 rpm 369 Keyb Ref Mot Pot 370 Spd Ctrl Pl VFX only		354	Flux optim	Off	
361 Motor Pot Non Volatile		355	Max Power	Off	
362 Preset Ref 1 0 rpm 363 Preset Ref 2 250 rpm 364 Preset Ref 3 500 rpm 365 Preset Ref 4 750 rpm 366 Preset Ref 5 1000 rpm 367 Preset Ref 6 1250 rpm 368 Preset Ref 7 1500 rpm 369 Keyb Ref Mot Pot 370 Spd Ctrl Pl VFX only 371 Spd Pl Auto Off VFX only	360	Prese	et Ref		
363 Preset Ref 2 250 rpm 364 Preset Ref 3 500 rpm 365 Preset Ref 4 750 rpm 366 Preset Ref 5 1000 rpm 367 Preset Ref 6 1250 rpm 368 Preset Ref 7 1500 rpm 369 Keyb Ref Mot Pot 370 Spd Ctrl Pl VFX only 371 Spd Pl Auto Off VFX only		361	Motor Pot	Non Volatile	
364 Preset Ref 3 500 rpm 365 Preset Ref 4 750 rpm 366 Preset Ref 5 1000 rpm 367 Preset Ref 6 1250 rpm 368 Preset Ref 7 1500 rpm 369 Keyb Ref Mot Pot 370 Spd Ctrl Pl VFX only 371 Spd Pl Auto Off VFX only		362	Preset Ref 1	0 rpm	
365 Preset Ref 4 750 rpm 366 Preset Ref 5 1000 rpm 367 Preset Ref 6 1250 rpm 368 Preset Ref 7 1500 rpm 369 Keyb Ref Mot Pot 370 Spd Ctrl Pl VFX only 371 Spd Pl Auto Off VFX only		363	Preset Ref 2	250 rpm	
366 Preset Ref 5 1000 rpm 367 Preset Ref 6 1250 rpm 368 Preset Ref 7 1500 rpm 369 Keyb Ref Mot Pot 370 Spd Ctrl Pl VFX only 371 Spd Pl Auto Off VFX only		364	Preset Ref 3	500 rpm	
367 Preset Ref 6 1250 rpm		365	Preset Ref 4	750 rpm	
368 Preset Ref 7 1500 rpm 369 Keyb Ref Mot Pot 370 Spd Ctrl Pl VFX only 371 Spd Pl Auto Off VFX only		366	Preset Ref 5	1000 rpm	
369 Keyb Ref Mot Pot		367	Preset Ref 6	1250 rpm	
370 Spd Ctrl Pl VFX only 371 Spd Pl Auto Off VFX only				1500 rpm	
371 Spd Pl Auto Off VFX only				Mot Pot	
	370	Spd	Ctrl PI		VFX only
372 Spd P Gain VFX only			Spd PI Auto	Off	VFX only
		372	Spd P Gain		VFX only

			Factory setting	Note/ Customer
	373	Spd I Time		VFX only
380	Proc	CtrlPID	4	
	381	PID Control	Off	
	382	PID Autotune	Off	
	383	PID P Gain	1.0	
	384	PID I Time	1.00s	
	385	PID D Time	0.00s	
	386	PID <minspd< td=""><td>Off</td><td></td></minspd<>	Off	
	387	PID Act Marg	0	
	388	PID Stdy Tst	Off	
	389	PID Stdy Mar	0	
390	Pum	p/Fan Ctrl	•	•
	391	Pump enable	Off	
	392	No of Drives	2	
	393	Select Drive	Sequence	
	394	Change Cond	Both	
	395	Change Timer	50h	
	396	Drives on Ch	0	
	397	Upper Band	10%	
	398	Lower Band	10%	
	399	Start Delay	0s	
	39A	Stop Delay	0s	
	39B	Upp Band Lim	0%	
	39C	Low Band Lim	0%	
	39D	Settle Start	0s	
	39E	TransS Start	60%	
	39F	Settle Stop	0s	
	39G	TransS Stop	60%	
	39H	Run Time 1	00:00:00	
		39H1 Rst Run Tm1	No	
	391	Run Time 2	00:00:00	
		39I1 Rst Run Tm2	No	
	39J	Run Time 3	00:00:00	
		39J1 Rst Run Tm3	No	
	39K	Run Time 4	00:00:00	
		39K1 Rst Run Tm4	No	
	39L	Run Time05	00:00:00	
		39L1 Rst Run Tm5	No	

					Factory setting	Note/ Customer
		39M	Run Ti	me 6	00:00:00	
			39M1	Rst Run Tm6	No	
		39N	Pump	123456		
		39P	No of	Backup	0	
	3A0	Cran	e Optio	n		VFX only
		3A1	Crane	enable	Off	VFX only
		3A2	Contro	ol	4-Speed	VFX only
		3A3	Crane	Relay 1	No trip	VFX only
		3A4	Crane	Relay 2	Brake	VFX only
		3A5	PreLim	nSwSpd		VFX only
				Spd H/R		VFX only
		3A7	Crawls	Spd L/L		VFX only
		3A8	Speed	2		VFX only
		3A9	Speed	3		VFX only
		3AA	Speed	4		VFX only
		3AB	Dev Ba	andwidt		VFX only
		3AC	Dev Ti	me	ms	VFX only
			LAFS		Off	VFX only
		3AG	Crane	N Function	Zero Pos	VFX only
400	Mon	itor/Pr	ot			
	410		Monito			
		411	Alarm	Select	Off	
			Alarm	•	Off	
			Ramp		Off	
			Start E		2s	
			Load 7	<u>,, </u>	Basic	
		416	Max A			
				MaxAlarmMar		
				MaxAlarmDel	0.1s	
		417		re alarm	T	
				MaxPreAlMar	10%	
				MaxPreAlDel	0.1s	
		418		e Alarm	Γ -	
				MinPreAlMar	10%	
				MinPreAlDel	0.1s	
		419			T	
			4191	MinAlarmMar	15%	
			4192	MinAlarmDel	0.1s	

						1
					Factory setting	Note/ Customer
		41A	Autose	et Alrm	No	
		41B	Norma	l Load	100%	
		41C	Load (Curve	•	
			41C1	Load Curve 1	100%	
			41C2	Load Curve 2	100%	
			41C3	Load Curve 3	100%	
			41C4	Load Curve 4	100%	
			41C5	Load Curve 5	100%	
			41C6	Load Curve 6	100%	
			41C7	Load Curve 7	100%	
			41C8	Load Curve 8	100%	
			41C9	Load Curve 9	100%	
		41D	MinAb	sMarg	3%	
	420		ess Pro			
		421	Low Vo	olt OR	On	
		422	Rotor	_ocked	Off	
		423	Motor	lost	Off	
		424	Overvo	olt Ctrl	On	
500	I/Os					
	510	An In	puts			
		511	AnIn1	Fc	Process Ref	
		512	AnIn1	Setup	4-20mA	
		513	AnIn1	Advn		
			5131	AnIn1 Min	4mA	
			5132	AnIn1 Max	10.00V/20.00mA	
			5133	AnIn1 Bipol	10.00V/20.00mA	
			5134	AnIn1 FcMin	Min	
				AnIn1 ValMin	0	
				AnIn1 FcMax	Max	
			5137	AnIn1 ValMax	0	
				AnIn1 Oper	Add+	
				AnIn1 Filt	0.1s	
			513A	AnIn1 Enabl	On	
			AnIn2		Off	
		515	AnIn2	Setup	4-20mA	
		516	AnIn2	Advan		
			5161	AnIn2 Min	4mA	
			5162	AnIn2 Max	20.00mA	

		Factory setting	Note/ Customer
5163 AnIn2 Bipol		20.00mA	
5164 AnIn2 FcMin		Min	
5165	AnIn2 ValMin	0	
5166	AnIn2 FcMax	Max	
5167	AnIn2 ValMax	0	
5168	AnIn2 Oper	Add+	
5169	AnIn2 Filt	0.1s	
516A	AnIn2 Enabl	On	
AnIn3	Fc	Off	
AnIn3	Setup	4-20mA	
AnIn3	Advan		
5191	AnIn3 Min	4mA	
5192	AnIn3 Max	20.00mA	
5193	AnIn3 Bipol	20.00mA	
5194	AnIn3 FcMin	Min	
5195	AnIn3 ValMin	0	
5196	AnIn3 FcMax	Max	
5197	Anin3 ValMax	0	
5198	AnIn3 Oper	Add+	
5199	AnIn3 Filt	0.1s	
519A	AnIn3 Enabl	On	
AnIn4	Fc	Off	
AnIn4	Setup	4-20mA	
AnIn4	Advan		
51C1	AnIn4 Min	4mA	
51C2	AnIn4 Max	20.00mA	
51C3	AnIn4 Bipol	20.00mA	
51C4	AnIn4 FcMin	Min	
51C5	AnIn4 ValMin	0	
51C6	AnIn4 FcMax	Max	
51C7	AnIn4 ValMax	0	
51C8	AnIn4 Oper	Add+	
51C9	AnIn4 Filt	0.1s	
51CA	AnIn4 Enabl	On	
	5164 5165 5166 5167 5168 5169 516A Anina: Anina: 5191 5192 5193 5194 5195 5196 5197 5198 5199 5190 5190 5110 5101 5102 5102 5103 5104 5105 5105 5105 5106 5107 5108 5109 5109 5100 51	5164 AnIn2 FcMin 5165 AnIn2 ValMin 5166 AnIn2 ValMax 5167 AnIn2 Oper 5168 AnIn2 Filt 5169 AnIn2 Enabl AnIn3 Fc AnIn3 Setup AnIn3 Advan 5191 5191 AnIn3 Min 5192 AnIn3 Max 5193 AnIn3 FcMin 5194 AnIn3 FcMin 5195 AnIn3 ValMin 5196 AnIn3 FcMax 5197 AnIn3 ValMax 5198 AnIn3 Oper 5199 AnIn3 Filt 5190 AnIn3 Filt 5191 AnIn3 Enabl AnIn4 Fc AnIn4 Min 5102 AnIn4 Min 5103 AnIn4 Bipol 5104 AnIn4 FcMin 5105 AnIn4 ValMin 5106 AnIn4 FcMax 5107 AnIn4 ValMin 5108 AnIn4 ValMax 5109 AnIn4 ValMax 5100 AnIn4 FcMax	5163 AnIn2 Bipol 20.00mA 5164 AnIn2 FcMin Min 5165 AnIn2 ValMin 0 5166 AnIn2 FcMax Max 5167 AnIn2 ValMax 0 5168 AnIn2 Oper Add+ 5169 AnIn2 Filt 0.1s 516A AnIn2 Enabl On AnIn3 Fc Off Off AnIn3 Setup 4-20mA AnIn3 Advan 5191 AnIn3 Min 4mA 5192 AnIn3 Max 20.00mA 5192 5193 AnIn3 Bipol 20.00mA 5194 5194 AnIn3 FcMin Min 5195 AnIn3 ValMin 0 0 5196 AnIn3 FcMax Max 5197 AnIn3 ValMax 0 0 5198 AnIn3 Filt 0.1s 0 5199 AnIn3 Enabl On 0 AnIn4 Fc Off 0 AnIn4 Setup 4-20mA 4-20mA <t< td=""></t<>

				Factory setting	Note/ Customer
520	Dig Ir	etuar			
		DigIn 1		RunL	
		DigIn 2		RunR	
		DigIn 3		Off	
	524	DigIn 4		Off	
	525	DigIn 5	j	Off	
	526	DigIn 6)	Off	
	527	DigIn 7	,	Off	
		DigIn 8		Reset	
	529	B(oard)1 Digln 1	Off	
	52A	B(oard)1 Digln 2	Off	
	52B	B(oard)1 DigIn 3	Off	
	52C	B(oard)2 DigIn 1	Off	
	52D	B(oard)2 DigIn 2	Off	
	52E	B(oard)2 DigIn 3	Off	
	52F	B(oard)3 DigIn 1	Off	
	52G	B(oard)3 Digln 2	Off	
	52H	B(oard)3 DigIn 3	Off	
530	An O	utputs			
	531	AnOut	1 Fc	Speed	
	532	AnOut	1 Setup	4-20mA	
	533	AnOut	1 Adv		
		5331	AnOut 1 Min	4mA	
		5332	AnOut 1 Max	20.0mA	
		5333	AnOut1Bipol	-10.00-10.00 V	
		5334	AnOut1 FcMin	Min	
		5335	AnOut1 VaMin	0	
		5336	AnOut1 FcMax	Max	
.=		5337	AnOut1 VaMax	0	
		AnOut2 FC AnOut2 Setup AnOut2 Advan 5361 AnOut 2 Min 5362 AnOut 2 Max		Torque	
	535			4-20mA	
	536				
				4mA	
				20.0mA	
		5363	AnOut2Bipol	-10.00-10.00 V	
		5364	AnOut2 FcMin		
		5365	AnOut2 VaMin	0	
		5366	AnOut2 FcMax	Max	

				Factory setting	Note/ Customer
	ſ	5367	AnOut2 VaMax	0	
540 D			7 HTO GLE TO HOLD		-
		DigOut	<u> </u>	Ready	
		DigOut		,	
550 R		_			
5	51	Relay 1	1	Trip	
5	52	Relay 2	2	Run	
5	53	Relay 3	3	Off	
5	54	B(oard)1 Relay 1	Off	
5	55	B1 Rel	ay 2	Off	
5	56	B1 Rel	ay 3	Off	
5	57	B2 Rel	ay 1	Off	
5	58	B2 Rel	ay 2	Off	
5	59	B2 Rel	ay 3	Off	
5	5A	B3 Rel	ay 1	Off	
5	5B	B3 Rel	ay 2	Off	
5	5C	B3 Rel	ay 3	Off	
5	5D	Relay A	Adv		
		55D1	Relay 1 Mode	N.O	
		55D2	Relay 2 Mode	N.O	
		55D3	Relay 3 Mode	N.O	
		55D4	B1R1 Mode	N.O	
		55D5	B1R2 Mode	N.O	
		55D6	B1R3 Mode	N.O	
		55D7	B2R1 Mode	N.O	
	L	55D8	B2R2 Mode	N.O	
	L	55D9	B2R3 Mode	N.O	
	L		B3R1 Mode	N.O	
	L		B3R2 Mode	N.O	
		55DC	B3R3 Mode	N.O	
560 V					
		VIO 1 I		Off	
		VIO 1		Off	
		VIO 2 I		Off	
		VIO 2 Source VIO 3 Dest		Off	
				Off	
		VIO 3 S		Off	
5	67	VIO 4 I	Jest	Off	

			İ	I	
_				Factory setting	Note/ Customer
	568	VIO 4 S	Source	Off	
	569	VIO 5 [Dest	Off	
	56A	VIO 5 S	Source	Off	
	56B	VIO 6 [Dest	Off	
	56C	VIO 6 S	Source	Off	
	56D	VIO 7 [Dest	Off	
	56E	VIO 7 S	Source	Off	
	56F	VIO 8 I	Dest	Off	
	56G	VIO 8 S	Source	Off	
600 Logic	al&Ti	mers		1	
610	Com	parators	S		
	611	CA1 S	etup		
_		6111	CA1 Value	Speed	
		6112	CA1 Level HI	300rpm	
		6113	CA1 Level LO	200rpm	
		6114	CA1 Type	Hysteresis	
		6115	CA1 Polar	Unipolar	
	612	CA2 S	etup		
=		6121	CA2 Value	Torque	
		6122	CA2 Level HI	20%	
		6123	CA2 Level LO	10%	
		6124	CA2 Type	Hysteresis	
		6125	CA2 Polar	Unipolar	
	613	CA3 S	etup		
_		6131	CA3 Value	Process Val	
		6132	CA3 Level HI	300rpm	
		6133	CA3 Level LO	200rpm	
		6134	САЗ Туре	Hysteresis	
		6135	CA3 Polar	Unipolar	
	614	CA4 S	etup		
_		6141	CA4 Value	Process Err	
		6142	CA4 Level HI	100 rpm	
		6143	CA4 Level LO	- 100 rpm	
		6144	CA4 Type	Window	
		6145	CA4 Polar	Bipolar	
	615	CD Se	tup		
		6151	CD1	Run	
		6152	CD2	DigIn 1	

				Factory setting	Note/ Customer
		6153	CD3	Trip	
		6154	CD4	Ready	
620	Logic	ΣΥ	Į	!	-
L	621	Y Comp 1		CA1	
	622	Y Operator 1		&	
	623	Y Com	np 2	!A2	
	624	Y Ope	rator 2	&	
	625	Y Com	np 3	CD1	
630	Logic	c Z			
	631	Z Com	ıp 1	CA1	
		Z Opei		&	
		Z Com		!A2	
	634	Z Opei	rator 2	&	
		Z Com	ıp 3	CD1	
640					
		Timer1	0	Off	
		Timer1		Off	
		643 Timer1 Delay 644 Timer 1 T1 645 Timer1 T2		0:00:00	
				0:00:00	
				0:00:00	
		Timer1	Value	0:00:00	
650				I	1
		Timer2	Ü	Off	
		Timer2		Off	
		Timer2		0:00:00	
		Timer:		0:00:00	
		Timer2		0:00:00	
440		Tmer2 Value		0:00:00	
660	Cour 661		or 1		
	001			Off	
			C1 Trig C1 Reset	Off	
		6613	C1 High Val	0	
		6614	C1 Low Val	0	
			C1 DecTimer	Off	
			C1 Value	0	
	662			<u> </u>	1
		6621	C2 Trig	Off	
			9		

CG Drives & Automation 51

				T		
					Factory setting	Note/ Customer
			6622	C2 Reset	Off	
			6623	C2 High Val	0	
			6624	C2 Low Val	0	
			6625	C2 DecTimer	Off	
			6629	C2 Value	0	
700	Oper	er/Status				
	710	Operation				
•		711 Process Val		ss Val		
	İ	712	Speed			
	İ	713	Torque)		
		714	Shaft F	Power		
		715	El Pow	/er		
	İ	716	Curren	nt		
	İ	717	Output	t volt		
			Freque	ency		
			DC Vo	ltage		
			Heatsi	nk Tmp		
	720	721 AC drive Status				
-						
	722 Warning 723 Digln Status 724 DigOut Status 725 AnIn 1 2		ng			
			DigIn S	Status		
			DigOu	t Status		
			Anln 1	2		
		726	Anln 3	4		
	ĺ	727	AnOut	1 2		
	ĺ	728	IO Stat	tus B1		
		729	IO Stat	tus B2		
		72A	IO Stat	tus B3		
		72B	Area D) Stat		
				Area D LSB		
			72B2 Area D MSB			
_		731 Run Time				
	730					
				00:00:00		
	732 Mains Time 733 Energy		Reset RunTm			
					00:00:00	
			33		kWh	
			7331	Rst Energy	No	

			Factory setting	Note/ Customer
800 View	TripL	og		
810	Trip I	Message (log list 1)		
	811	Process Value		
	812	Speed		
	813	Torque		
	814	Shaft Power		
	815	El Power		
	816	Current		
	817	Output voltage		
	818	Frequency		
	819	DC voltage		
	81A	Heatsink Tmp		
	81B	PT100_1, 2, 3		
	81C	VSD Status		
	81D	DigIn status		
	81E	DigOut status		
	81F	AnIn 1 2		
	81G	AnIn 3 4		
	81H	AnOut 1 2		
	811	IO Status B1		
	81J	IO Status B2		
	81K	IO Status B3		
		Run Time		
	81M	Mains Time		
	81N	Energy		
		Process reference		
		VIO Status		
		Message 821- 82P (log	•	
		Message 831 - 83P (log		
		Message 841 - 84P (log		
		Message 851 - 85P (log		
		Message 861 - 86P (log		
		Message 871 - 87P (log		
		Message 881 - 88P (log		
890	Trip I	Message 891 - 89P (log	list 9)	
8A0	Rese	et Trip	No	

CG Drives & Automation 53

					Factory setting	Note/ Customer
900	Syste	em Da	ata			
	920	AC o	Irive Dat	ta		
		921	AC driv	ve Type		
		922	Softwa	ire		
			9221	Build Info		
			9222	Build ID		
		923	Unit na	ime	0	

CG Drives & Automation

www.cgglobal.com / www.emotron.com